ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0384, W0374, W0705, W0370, W0372, W0380, W0699	Own Use Rd, 1st Main Rd, NA, 9th Crs Lakshmi Sagar Lyt	Attur layout
Segment No.	**Total Length (m)**	
3/C-W0384/S115036	703.35	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	361.44	77.568269	13.101362	77.568054	13.098102	M0008	W0370
2	341.91	77.568848	13.101237	77.568623	13.098154	M0008	W0370

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drain attur layout in ward no 03 (Balance roads) Yelahanka Satellite Town Sub division Yelahanka zone	5000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements to roads and drain attur layout in ward no 03 (Balance roads) Yelahanka Satellite Town Sub division Yelahanka zone	003-17-000074
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/ (YNK.D)/WO/69/2017-18	16/06/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/09/2017	14/09/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0384, W0374, W0705, W0370,

ಸಹಾಯಕ ಅಭಿಯಂತರರು, ವಾರ್ಡ್ ಸಂ-03
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು - 64

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬ.ಬ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

9863065

Field Inspection Details

Number of Trees
6

Any Other Information

Name
CHANDRAKANTH

Date of Inspection
23/12/2017

Remarks
COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0384, W0374, W0705, W0370,

ಸಹಾಯಕ ಅಭಿಯಂತರರು/ವಾರ್ಡ್ ಸಂ-03
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು - 64

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: YELAHANKA Ward No: 3 Ward Name: Alturu Street ID: W0384, W0374, W0705, W0370,

ಸಹಾಯಕ ಅಭಿಯಂತರರು, ವಾರ್ಡ್ ಸಂ-03
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು – 64

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106